

Data transfer via internet or medium

In-house CAD: VISI-CAD (wkf)

2D interfaces: wkf / dxf / dwg
pdf only when combined with wkf / dxf or dwg

Split icons, patterns and blocks in single elements, change polylines into line segments and curves.

3D interfaces: x_t / stp
Direct interfaces: Catia, Pro-E, Unigraphics
No processing: igs

Required data

- » Parts list with design details (tolerances, surface roughness, colour tables, ...)
- » Detailed drawings, with dimensions and tolerances
- » Assembly drawing including accessories
- » 3D data
- » Complete standard moulds split in single layers
- » Thread details (metric, inch, pitch)

Send data to: av@meusburger.com

The contours drawn must be in accordance with the dimensioning (for processing with a CAM workstation)
With respect to 2D+3D data, we assume they are identical.

Subsequent modifications or amendments have to be identified by an amendment index.